

Title of Change:	FSUSB43L10X datasheet change	
Effective date:	06 Jun 2022	
Contact information:	Contact your local onsemi Sales Office or Jeremy.Ferris@onsemi.com	
Type of notification:	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.	
Change Category:	Datasheet	
Change Sub-Category(s):	Datasheet/Product Doc change	
Sites Affected:		
onsemi Sites	External Foundry/Subcon Sites	
None	None	
Description and Purpose:		
<p>The max Operating Temperature (T_A) increased to +125C.</p> <p>The onsemi Capacitance parameter (C_{ON}) typical value was incorrect for the defined test conditions and has been updated from 3.7pF to 5.5pF.</p> <p>The change will not impact form, fit, or function of product.</p>		
List of Affected Standard Parts:		
<p>Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the <u>PCN Customized Portal</u>.</p>		
FSUSB43L10X		

Appendix A: Changed Products

PCN#: PB24777X
Issue Date: Jun 06, 2022

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
FSUSB43L10X		FSUSB43L10X		