

Product Obsolescence Memo

TBU® HIGH-SPEED PROTECTORS

REVISED June 26, 2014



Bourns® Model TBU-KE Series TBU® High-Speed Protectors to be Discontinued

In accordance with our ongoing product lifecycle management procedure, Bourns has identified select TBU® High-Speed Protector products that will be transferred to an End of Product Life status. A lack of sales volume and diminishing demand necessitates this action.

The Model TBU-DT Series High-Speed Protector is recommended as the alternate model. The Model TBU-DT Series is not pin-pin compatible. It is functionally equivalent to Model TBU-KE but is packaged differently. Please contact the Bourns team of Field Application Engineers if you have any questions regarding the suggested replacement part numbers and your application requirements.

Obsolete Part Numbers	Replacement Part Numbers*
TBU-KE025-050-WH	TBU-DT065-100-WH
TBU-KE025-100-WH	TBU-DT065-100-WH
TBU-KE025-200-WH	TBU-DT065-200-WH
TBU-KE025-300-WH	TBU-DT065-300-WH
TBU-KE025-500-WH	TBU-DT065- 500 -WH
TBU-KE040-050-WH	TBU-DT065-100-WH
TBU-KE040-100-WH	TBU-DT065-100-WH
TBU-KE040-200-WH	TBU-DT065-200-WH
TBU-KE040-300-WH	TBU-DT065-300-WH
TBU-KE040-500-WH	TBU-DT065- 500 -WH
TBU-KE050-050-WH	TBU-DT065-100-WH
TBU-KE050-100-WH	TBU-DT065-100-WH
TBU-KE050-200-WH	TBU-DT065-200-WH
TBU-KE050-300-WH	TBU-DT065-300-WH
TBU-KE050-500-WH	TBU-DT065- 500 -WH

* See data sheet for more specifications.

Please plan for the following deadlines:

Last time buy date: April 30, 2015

Last time ship date: June 30, 2015

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).