



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M001040

DATE: 12-Aug-2021

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1677E+	N/A	11-Feb-2022	10-Aug-2022	Part can no longer be manufactured
Discontinuance	DS28E01P-W18+1	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E01P-W18+1T	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E01P-W18+2	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E01P-W18+2T	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E01Q-W14+1T	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+1	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+1T	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+3	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+3T	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+4	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+4T	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+5	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+5T	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+7	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+7T	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+8	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+8T	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02Q-W01+3T	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02Q-W01+4T	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	DS28E02Q-W01+6T	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX17710GB+	N/A	12-Aug-2021	08-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX333EPP+	N/A	11-Feb-2022	10-Aug-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 12-Sep-2021