

Product Change Notification 33662 is complete and has been sent to approved customers. Please e-mail QA_PCN_SUPPORT@micron.com if you have any questions regarding this Product Change Notification.



Micron Technology,
Inc.
8000 S. Federal Way
PO Box 6
Boise, ID United
States

eMCP 8GB+8Gb 221b End of Life

PCN: 33662

Published: 2020-05-19

Type:	End of Life
Description:	Micron will End of Life J95E eMCP 8GB+8Gb 221b with no replacement
Reason:	Better Align With Industry Standard, Change in Market Demand
Product Affected:	eMCP 8GB+8Gb 221b (J95E) product listed below

Affected Micron Part Number	Recommended Replacement	Customer Part Number
<u>Component</u>		
MT29TZZZ8D5JKERL-107 W.95E		

*Materials that have been ordered are in **bold**.

Method of Identification:	Marketing Part Number
Micron Sites Affected:	All Sites

Last Purchase Date*: 2020-11-19

Last Shipment Date: 2021-05-19

Early placement of orders is encouraged as an increase in demand for this product could potentially exceed Micron's ability to meet all requests. All products from a previously accepted order that have not shipped as of the last-time purchase date will be considered non-cancelable and non-returnable. Changes to confirmed request dates will also require written approval by Micron. Should additional supply be available after the last-time purchase date, Micron may accept orders for product and such orders placed will be considered non-cancelable and non-returnable.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.