

Product Obsolescence Notification

Issue Date: 10/12/18

Dear Customer:

Broadcom Inc. announces the following products will transition from eutectics bumps within package to lead free bumps for full RoHS6 compliance without exemptions. New ordering part number, but no change to Form Function and Features:

Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Replacement Part Number
BCM53394A0IFSBG	Switch	4/15/2019	10/15/2019	BCM53394A0IFSBLG
BCM53394A0KFSBG	Switch	4/15/2019	10/15/2019	BCM53394A0KFSBLG
BCM56044B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56044B0KFSBLG
BCM56132B1KFSBG	Switch	4/15/2019	10/15/2019	BCM56132B1KFSBLG
BCM56134B1IFSB	Switch	4/15/2019	10/15/2019	BCM56134B1IFSBLG
BCM56134B1KFSB	Switch	4/15/2019	10/15/2019	BCM56134B1KFSBLG
BCM56134LB1KFSBG	Switch	4/15/2019	10/15/2019	No replacement
BCM56230B1IFSBG	Switch	4/15/2019	10/15/2019	BCM56230B1IFSBLG
BCM56230B1KFSBG	Switch	4/15/2019	10/15/2019	BCM56230B1KFSBLG
BCM56231B1IFSBG	Switch	4/15/2019	10/15/2019	BCM56231B1IFSBLG
BCM56240B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56240B0IFSBLG
BCM56242B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56242B0IFSBLG
BCM56242XB0IFSBG	Switch	4/15/2019	10/15/2019	BCM56242XB0IFSBLG
BCM56243B0IFSBG	Switch	4/15/2019	10/15/2019	No replacement
BCM56243XB0IFSBG	Switch	4/15/2019	10/15/2019	BCM56243XB0IFSBLG
BCM56245B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56245B0IFSBLG
BCM56246B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56246B0IFSBLG
BCM56320B1IFSBG	Switch	4/15/2019	10/15/2019	BCM56320B1IFSBLG
BCM56321B1KFSBG	Switch	4/15/2019	10/15/2019	BCM56321B1KFSBLG
BCM56333B1IFSB	Switch	4/15/2019	10/15/2019	BCM56333B1IFSBLG
BCM56333B1IFSBG	Switch	4/15/2019	10/15/2019	BCM56333B1IFSBLG
BCM56334B1IFSB	Switch	4/15/2019	10/15/2019	BCM56334B1IFSBLG
BCM56334B1IFSBG	Switch	4/15/2019	10/15/2019	BCM56334B1IFSBLG
BCM56334B1KFSB	Switch	4/15/2019	10/15/2019	BCM56334B1KFSBLG
BCM56338B1IFSB	Switch	4/15/2019	10/15/2019	BCM56338B1IFSBLG
BCM56338B1IFSBG	Switch	4/15/2019	10/15/2019	BCM56338B1IFSBLG
BCM56338B1KFSBG	Switch	4/15/2019	10/15/2019	BCM56338B1KFSBLG
BCM56440B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56440B0IFSBLG
BCM56440TB0IFSBG	Switch	4/15/2019	10/15/2019	BCM56440TB0IFSBLG
BCM56440TB0KFSBG	Switch	4/15/2019	10/15/2019	BCM56440TB0KFSBLG
BCM56440XB0IFSB	Switch	4/15/2019	10/15/2019	BCM56440XB0IFSBLG
BCM56440XB0IFSBG	Switch	4/15/2019	10/15/2019	BCM56440XB0IFSBLG
BCM56440XB0KFSBG	Switch	4/15/2019	10/15/2019	BCM56440XB0KFSBLG
BCM56441TB0KFSBG	Switch	4/15/2019	10/15/2019	BCM56441TB0KFSBLG
BCM56442B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56442B0IFSBLG
BCM56442B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56442B0KFSBLG
BCM56443TB0KFSBG	Switch	4/15/2019	10/15/2019	BCM56443TB0KFSBLG
BCM56443TB0IFSBG	Switch	4/15/2019	10/15/2019	No replacement
BCM56443XB0IFSBG	Switch	4/15/2019	10/15/2019	BCM56443XB0IFSBLG
BCM56445B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56445B0IFSBLG

Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Replacement Part Number
BCM56445B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56445B0KFSBLG
BCM56445XB0IFSBG	Switch	4/15/2019	10/15/2019	BCM56445XB0IFSBLG
BCM56445XB0KFSBG	Switch	4/15/2019	10/15/2019	BCM56445XB0KFSBLG
BCM56446B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56446B0IFSBLG
BCM56447B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56447B0KFSBLG
BCM56448B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56448B0IFSBLG
BCM56448XB0KFSBG	Switch	4/15/2019	10/15/2019	BCM56448XB0KFSBLG
BCM56520B0IFSB	Switch	4/15/2019	10/15/2019	BCM56520B0IFSBLG
BCM56520B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56520B0IFSBLG
BCM56521B0KFSB	Switch	4/15/2019	10/15/2019	BCM56521B0KFSBLG
BCM56521B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56521B0KFSBLG
BCM56524B0IFSB	Switch	4/15/2019	10/15/2019	BCM56524B0IFSBLG
BCM56524B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56524B0IFSBLG
BCM56524B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56524B0KFSBLG
BCM56526B0IFSB	Switch	4/15/2019	10/15/2019	BCM56526B0IFSBLG
BCM56526B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56526B0IFSBLG
BCM56526B0KFSB	Switch	4/15/2019	10/15/2019	BCM56526B0KFSBLG
BCM56526B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56526B0KFSBLG
BCM56538B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56538B0KFSBLG
BCM56538LB0KFSBG	Switch	4/15/2019	10/15/2019	No replacement
BCM56541XB0IFSBG	Switch	4/15/2019	10/15/2019	No replacement
BCM56542B0KFSBG	Switch	4/15/2019	10/15/2019	No replacement
BCM56542XB0KFSBG	Switch	4/15/2019	10/15/2019	BCM56542XB0KFSBLG
BCM56543B0IFSBG	Switch	4/15/2019	10/15/2019	No replacement
BCM56543B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56543B0KFSBLG
BCM56624B2KFSB	Switch	4/15/2019	10/15/2019	BCM56624B2KFSBLG
BCM56626B2KFSB	Switch	4/15/2019	10/15/2019	BCM56626B2KFSBLG
BCM56628B2KFSB	Switch	4/15/2019	10/15/2019	BCM56628B2KFSBLG
BCM56630B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56630B0IFSBLG
BCM56630B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56630B0KFSBLG
BCM56634B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56634B0IFSBLG
BCM56634B0KFSB	Switch	4/15/2019	10/15/2019	BCM56634B0KFSBLG
BCM56634B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56634B0KFSBLG
BCM56636B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56636B0IFSBLG
BCM56636B0KFSB	Switch	4/15/2019	10/15/2019	BCM56636B0KFSBLG
BCM56636B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56636B0KFSBLG
BCM56638B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56638B0IFSBLG
BCM56638B0KFSB	Switch	4/15/2019	10/15/2019	BCM56638B0KFSBLG
BCM56638B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56638B0KFSBLG
BCM56639B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56639B0IFSBLG
BCM56639B0KFSB	Switch	4/15/2019	10/15/2019	BCM56639B0KFSBLG
BCM56639B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56639B0KFSBLG
BCM56644B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56644B0IFSBLG
BCM56685B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56685B0KFSBLG
BCM56689B0IFSB	Switch	4/15/2019	10/15/2019	BCM56689B0IFSBLG
BCM56689B0IFSBG	Switch	4/15/2019	10/15/2019	BCM56689B0IFSBLG
BCM56689B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56689B0KFSBLG
BCM56720B0KFSB	Switch	4/15/2019	10/15/2019	BCM56720B0KFSBLG
BCM56720B0IFSBG	Switch	4/15/2019	10/15/2019	No replacement
BCM56725B0KFSB	Switch	4/15/2019	10/15/2019	BCM56725B0KFSBLG
BCM56742A1KFRBG	Switch	4/15/2019	10/15/2019	BCM56742A1KFRBLG
BCM56742A1KFTBG	Switch	4/15/2019	10/15/2019	No replacement
BCM56744A1KFRB	Switch	4/15/2019	10/15/2019	BCM56744A1KFRBLG
BCM56744A1KFRBG	Switch	4/15/2019	10/15/2019	BCM56744A1KFRBLG
BCM56744A1KFTBG	Switch	4/15/2019	10/15/2019	BCM56744A1KFTBLG
BCM56745A4KFRB	Switch	4/15/2019	10/15/2019	BCM56745A4KFRBLG
BCM56745A4KFRBG	Switch	4/15/2019	10/15/2019	BCM56745A4KFRBLG

Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Replacement Part Number
BCM56746A1KFRB	Switch	4/15/2019	10/15/2019	BCM56746A1KFRBLG
BCM56746A1KFRBG	Switch	4/15/2019	10/15/2019	BCM56746A1KFRBLG
BCM56746A1KFTBG	Switch	4/15/2019	10/15/2019	BCM56746A1KFTBLG
BCM56750A2IFSBG	Switch	4/15/2019	10/15/2019	BCM56750A2IFSBLG
BCM56750A2KFSBG	Switch	4/15/2019	10/15/2019	BCM56750A2KFSBLG
BCM56820B0KFSB	Switch	4/15/2019	10/15/2019	BCM56820B0KFSBLG
BCM56820B0KFSBG	Switch	4/15/2019	10/15/2019	BCM56820B0KFSBLG
BCM56821B0IFSB	Switch	4/15/2019	10/15/2019	BCM56821B0IFSBLG
BCM56821B0KFSB	Switch	4/15/2019	10/15/2019	BCM56821B0KFSBLG
BCM56822B0KFSB	Switch	4/15/2019	10/15/2019	BCM56822B0KFSBLG
BCM56825B0KFSB	Switch	4/15/2019	10/15/2019	BCM56825B0KFSBLG
BCM56841A4KFRB	Switch	4/15/2019	10/15/2019	BCM56841A4KFRBLG
BCM56841A4KFRBG	Switch	4/15/2019	10/15/2019	BCM56841A4KFRBLG
BCM56841B1KFRBG	Switch	4/15/2019	10/15/2019	BCM56841B1KFRBLG
BCM56842A1IFRBG	Switch	4/15/2019	10/15/2019	BCM56842A1IFRBLG
BCM56842A1IFTBG	Switch	4/15/2019	10/15/2019	BCM56842A1IFTBLG
BCM56842A1KFRB	Switch	4/15/2019	10/15/2019	BCM56842A1KFRBLG
BCM56842A1KFRBG	Switch	4/15/2019	10/15/2019	BCM56842A1KFRBLG
BCM56842A1KFTBG	Switch	4/15/2019	10/15/2019	BCM56842A1KFTBLG
BCM56843A4IFRBG	Switch	4/15/2019	10/15/2019	No replacement
BCM56843A4KFRBG	Switch	4/15/2019	10/15/2019	BCM56843A4KFRBLG
BCM56843B1KFRBG	Switch	4/15/2019	10/15/2019	BCM56843B1KFRBLG
BCM56844A1IFRBG	Switch	4/15/2019	10/15/2019	BCM56844A1IFRBLG
BCM56844A1KFRBG	Switch	4/15/2019	10/15/2019	BCM56844A1KFRBLG
BCM56844A1KFTBG	Switch	4/15/2019	10/15/2019	BCM56844A1KFTBLG
BCM56845A4KFRBG	Switch	4/15/2019	10/15/2019	BCM56845A4KFRBLG
BCM56845B1KFRBG	Switch	4/15/2019	10/15/2019	BCM56845B1KFRBLG
BCM56846A1IFRBG	Switch	4/15/2019	10/15/2019	BCM56846A1IFRBLG
BCM56846A1IFTBG	Switch	4/15/2019	10/15/2019	BCM56846A1IFTBLG
BCM56846A1KFRB	Switch	4/15/2019	10/15/2019	BCM56846A1KFRBLG
BCM56846A1KFRBG	Switch	4/15/2019	10/15/2019	BCM56846A1KFRBLG
BCM56846A1KFTBG	Switch	4/15/2019	10/15/2019	BCM56846A1KFTBLG
BCM56846LA1KFRBG	Switch	4/15/2019	10/15/2019	No replacement
BCM56849A1KFRBG	Switch	4/15/2019	10/15/2019	No replacement
BCM56850XA2KFSBG	Switch	4/15/2019	10/15/2019	BCM56850XA2KFSBLG
BCM56851A2IFSBG	Switch	4/15/2019	10/15/2019	BCM56851A2IFSBLG
BCM56853A2KFSBG	Switch	4/15/2019	10/15/2019	BCM56853A2KFSBLG
BCM56854XA2IFSBG	Switch	4/15/2019	10/15/2019	BCM56854XA2IFSBLG
BCM56855A2IFSBG	Switch	4/15/2019	10/15/2019	BCM56855A2IFSBLG
BCM56855A2KFSBG	Switch	4/15/2019	10/15/2019	BCM56855A2KFSBLG
BCM88360A0IFSBG	Switch	4/15/2019	10/15/2019	BCM88360A0IFSBLG
BCM88360A0KFSBG	Switch	4/15/2019	10/15/2019	BCM88360A0KFSBLG
BCM88361A0IFSBG	Switch	4/15/2019	10/15/2019	BCM88361A0IFSBLG
BCM88361A0KFSBG	Switch	4/15/2019	10/15/2019	BCM88361A0KFSBLG
BCM88460A0IFSBG	Switch	4/15/2019	10/15/2019	BCM88460A0IFSBLG
BCM88460A0KFSBG	Switch	4/15/2019	10/15/2019	BCM88460A0KFSBLG
BCM88560A0KFSBG	Switch	4/15/2019	10/15/2019	BCM88560A0KFSBLG
BCM88562A0KFSBG	Switch	4/15/2019	10/15/2019	BCM88562A0KFSBLG
BCM88652B1KFSBWG	Switch	4/15/2019	10/15/2019	No replacement
BCM88660A0KFSB	Switch	4/15/2019	10/15/2019	BCM88660A0KFSBLG
BCM88660A0KFSBG	Switch	4/15/2019	10/15/2019	BCM88660A0KFSBLG
BCM88661A0KFSBG	Switch	4/15/2019	10/15/2019	BCM88661A0KFSBLG
BCM88664A0KFSBG	Switch	4/15/2019	10/15/2019	BCM88664A0KFSBLG
BCM88664LA0KFSBG	Switch	4/15/2019	10/15/2019	No replacement
BCM88732B2KFSBG	Switch	4/15/2019	10/15/2019	BCM88732B2KFSBLG
BCM88752KFSBG	Switch	4/15/2019	10/15/2019	No replacement
BCM88753B0KFSBG	Switch	4/15/2019	10/15/2019	BCM88753B0KFSBLG



Please provide your Broadcom Inc. Sales Office with your lifetime Last Time Buy order requirements (LTB) for the above products no later than the date noted in the above table. These orders are non-cancelable, non-returnable and cannot be rescheduled. Orders received after the Last Time Buy order (LTB) date noted in the above table cannot be accepted.

The last requested delivery date for these orders may not be later than the LTS date noted in the above table. Due to inherent variations in yields, Broadcom Inc. reserves the right to ship up to 5% under the original last time buy quantity, and this quantity will fully satisfy Broadcom Inc's obligation to deliver that product under this last time buy agreement.

Please contact your Broadcom Inc field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.