

# Product / Process Change Notification



N° 2007-063-A

|  |            |
|--|------------|
| ■ Last order date of unchanged product:    | 2009-06-30 |
| ■ Last delivery date of unchanged product: | 2009-12-31 |

| DISCONTINUED          |               |               | NEW (REPLACEMENT) |               |               |
|-----------------------|---------------|---------------|-------------------|---------------|---------------|
| Device                | Ordering Code | Package       | Device            | Ordering Code | Package       |
| BTS443P               | SP000012528   | P-TO252-5-1   | BTS443P           | SP000264198   | PG-TO252-5-11 |
| BTS443P               | SP000012527   | P-TO252-5-1   | BTS443P           | SP000264198   | PG-TO252-5-11 |
| BTS443P               | SP000012530   | P-TO252-5-1   | BTS443P           | SP000264198   | PG-TO252-5-11 |
| BTS443P 4287AB        | SP000012526   | P-TO252-5-1   | BTS443P           | SP000264198   | PG-TO252-5-11 |
| BTS650P               | SP000011287   | P-TO220-7-3   | BTS50055-1TMB     | SP000385907   | PG-TO220-7-11 |
| BTS650P E3180A        | SP000011289   | P-TO220-7-180 | BTS50055-1TMA     | SP000385906   | PG-TO220-7-4  |
| BTS650P E3180A 1983AA | SP000011295   | P-TO220-7-180 | BTS50055-1TMA     | SP000385906   | PG-TO220-7-4  |
| BTS6510B              | SP000012532   | P-TO220-7-180 | BTS50055-1TMC     | SP000385908   | PG-TO220-7-4  |
| BTS660P               | SP000012535   | P-TO220-7-3   | BTS50085-1TMB     | SP000385912   | PG-TO220-7-11 |
| BTS660P E3180A        | SP000012536   | P-TO220-7-180 | BTS50085-1TMA     | SP000385911   | PG-TO220-7-4  |

If you have any questions, please do not hesitate to contact your local Sales office.