




# PRODUCT OBSOLESCENCE MEMO

## TBU® HIGH-SPEED PROTECTORS



### Bourns® Model TBU-PL050-100-WH and TBU-PL050-200-WH *TBU® High-Speed Protectors to be Discontinued*

Riverside, California – December 22, 2021 – In accordance with our product life cycle management procedure, Bourns has transferred the [Model TBU-PL050-100-WH and TBU-PL050-200-WH TBU® High-Speed Protectors](#) to an End of Product Life status effective immediately. A lack of sales volume and diminishing demand necessitates this action.

The [Model TBU-PL060-100-WH and TBU-PL060-200-WH](#) are the recommended replacement part numbers. The form, fit and function of the suggested replacement parts are not identical to the discontinued parts. However, the specifications of the suggested replacement [Model TBU-PL060-100-WH and TBU-PL060-200-WH](#) are likely to be substitutable for typical applications. Please refer to the Bourns data sheet for more information.

| Obsolete Part Number | Recommended Replacement Part Number |
|----------------------|-------------------------------------|
| TBU-PL050-100-WH     | TBU-PL060-100-WH                    |
| TBU-PL050-200-WH     | TBU-PL060-200-WH                    |

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

FU2111