



8755 W. Higgins Road  
Suite 500  
Chicago, Illinois USA 60631

April 11, 2022

PCN EIC-1102 Assembly Facility Change

**Product Change Notification for Littelfuse Power Solid State Relays packaged in I4-PAC, ISOPLUS-264, and Super SIP DCB-based assemblies.**

To our valued customers,

IXYS Integrated Circuits Division (ICD), now part of Littelfuse, would like to notify you that we will transfer and consolidate the assembly and test process of the below products to another facility, also in the Philippines.

CPC1708J	CPC1779J	CPC1918J	CPC1978J
CPC1709J	CPC1786J	CPC1927J	CPC1979J
CPC1718J	CPC1788J	CPC1967J	CPC1986J
CPC1727J	CPC1908J	CPC1968J	CPC1988J
CPC1777J	CPC1909J	CPC1977J	CPC40055ST

Please note: PCN 1097 previously issued for part number CPC1998J. Therefore, part is not included in this PCN.

Below are the detail changes associated with this transfer and consolidation:

- 1) Silicon Die : No Change
- 2) Assembly Bill of Materials : No Change
- 3) Assembly Process Flow : No Change
- 4) Assembly Equipment : Equal or Better
- 5) Test Equipment : No Change
- 6) Marking & Labeling : See details below
- 7) Form, fit, function changes : No Change
- 8) Part number changes : No Change
- 9) Effective date : April 2022

DESCRIPTION	CHANGE (Y/N)	REMARKS
<b>Unit Marking</b>		
Logo	N	No change
UL Sign	N	No change
Trademark Sign	N	No change
Product Name	N	No change
Date Code	N	No change
Assembly Line Code	Y	Kit number prefix changes from P to T
<b>Box Label</b>		
Logo	N	No change
Qty per Box	N	No change
Part Number	N	No change
Lot No	Y	Kit number prefix changes from P to T
Country of Origin	N	No change
Lot ID	N	No change
Assy Line Code	N	No change
Product code	N	No change
<b>Tube Label</b>		
Logo	N	No change
Qty per Box	N	No change

This notification is for your information. If you have any questions or concerns, please contact your local sales team. We value your business and look forward to assisting you whenever possible.

If you have any other questions or concerns, please contact your local Littelfuse sales representative or Product Manager below for further assistance.

