



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631
www.littelfuse.com

LF PCN A0111: Notification for expansion of MIDI 0498 series

November 14, 2016

Dear Valued Customer,

As part of our process to maintain capability and capacity on standard product lines sold to multiple customers, Littelfuse is taking the following actions for the 0498 MIDI fuse series:

Littelfuse will add one assembly machine to expand capacity. This line is a copy of the machine that is used to build our MIDI fuses in our manufacturing plant in Suzhou, China. There are no changes to the rest of the current assembly equipment installed in the Piedras Negras, Mexico plant. This will be additional capacity and this action is being taken to protect supply. The new equipment will have no impact on the Form, Fit, or Function of the product.

The target date for the SOP of this line is November 21, 2016.

Impacted Materials:

Please refer to attached list for impacted materials.

Please contact your local Littelfuse representative if you have any additional questions. We will be pleased to answer any questions you may have. Thank you for your continued support.

Best Regards,

Aram Tamez

Aram Tamez
Littelfuse Automotive Business Unit
atamez@littelfuse.com

LFPCN_A0111 Affected Parts List

| Material | Material Description |
|-----------------|---|
| 0498023.M | Fuse - Midi 32VDC 23A 1000-pc |
| 0498030.M | Fuse - Midi 32VDC 30A 1000-pc |
| 0498040.M | Fuse - Midi 32VDC 40A 1000-pc |
| 0498050.M | Fuse - Midi 32VDC 50A 1000-pc |
| 0498060.M | Fuse - Midi 32VDC 60A 1000-pc |
| 0498070.M | Fuse - Midi 32VDC 70A 1000-pc |
| 0498080.M | Fuse - Midi 32VDC 80A 1000-pc |
| 0498100.M | Fuse - Midi 32VDC 100A 1000-pc |
| 0498125.M | Fuse - Midi 32VDC 125A 1000-pc |
| 0498150.M | Fuse - Midi 32VDC 150A 1000-pc |
| 0498175.M | Fuse - Midi 32VDC 175A 1000-pc |
| 0498200.M | Fuse - Midi 32VDC 200A 1000-pc |
| 0498030.MXT | Fuse - Midi 32VDC w/Clear Housing 30A |
| 0498040.MXT | Fuse - Midi 32VDC w/Clear Housing 40A |
| 0498050.MXT | Fuse - Midi 32VDC w/Clear Housing 50A |
| 0498060.MXT | Fuse - Midi 32VDC w/Clear Housing 60A |
| 0498070.MXT | Fuse - Midi 32VDC w/Clear Housing 70A |
| 0498080.MXT | Fuse - Midi 32VDC w/Clear Housing 80A |
| 0498100.MXT | Fuse - Midi 32VDC w/Clear Housing 100A |
| 0498125.MXT | Fuse - Midi 32VDC w/Clear Housing 125A |
| 0498150.MXT | Fuse - Midi 32VDC w/Clear Housing 150A |
| 0498175.MXT | Fuse - Midi 32VDC w/Clear Housing 175A |
| 0498200.MXT | Fuse - Midi 32VDC w/Clear Housing 200A |
| 0498030.MXM6 | Fuse - Midi 32VDC w/ M6 Holes 30A |
| 0498040.MXM6 | Fuse - Midi 32VDC w/ M6 Holes 40A |
| 0498050.MXM6 | Fuse - Midi 32VDC w/ M6 Holes 50A |
| 0498060.MXM6 | Fuse - Midi 32VDC w/ M6 Holes 60A |
| 0498070.MXM6 | Fuse - Midi 32VDC w/ M6 Holes 70A |
| 0498080.MXM6 | Fuse - Midi 32VDC w/ M6 Holes 80A |
| 0498100.MXM6 | Fuse - Midi 32VDC w/ M6 Holes 100A |
| 0498125.MXM6 | Fuse - Midi 32VDC w/ M6 Holes 125A |
| 0498150.MXM6 | Fuse - Midi 32VDC w/ M6 Holes 150A |
| 0498175.MXM6 | Fuse - Midi 32VDC w/ M6 Holes 175A |
| 0498200.MXM6 | Fuse - Midi 32VDC w/ M6 Holes 200A |
| 0498030.MX1M5 | Fuse - Midi 32VDC M5 1-hole 30A |
| 0498040.MX1M5 | Fuse - Midi 32VDC M5 1-hole 40A |
| 0498050.MX1M5 | Fuse - Midi 32VDC M5 1-hole 50A |
| 0498060.MX1M5 | Fuse - Midi 32VDC M5 1-hole 60A |
| 0498070.MX1M5 | Fuse - Midi 32VDC M5 1-hole 70A |
| 0498080.MX1M5 | Fuse - Midi 32VDC M5 1-hole 80A |
| 0498100.MX1M5 | Fuse - Midi 32VDC M5 1-hole 100A |
| 0498125.MX1M5 | Fuse - Midi 32VDC M5 1-hole 125A |
| 0498150.MX1M5 | Fuse - Midi 32VDC M5 1-hole 150A |
| 0498175.MX1M5 | Fuse - Midi 32VDC M5 1-hole 175A |
| 0498200.MX1M5 | Fuse - Midi 32VDC M5 1-hole 200A |
| 0498150.MXTM6 | Fuse - Midi 32V Clear Hsng M6 Hole 150A |
| 0498175.MXTM6 | Fuse - Midi 32V Clear Hsng M6 Hole 175A |
| 0498200.MXTM6 | Fuse - Midi 32V Clear Hsng M6 Hole 200A |