



Product Change Notification

TE Connectivity

Product Change Notification: P-16-012507

PCN Date: 12-JAN-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

lubricant changed from NYETACT 561J-50-AG to NYETACT 568J-50-UV

Description of Changes

The NYE performance lubricant applied to these terminals is currently NYETACT 561J-50-AG, it will be transitioned to NYETACT 568J-50-UV. Therefore note detailing the lubricant will change to specify NYETACT 568J-50-UV. This is the same lubricant, just a new p/n from NYE Lubricants, Inc. to due component supplier change. There is no change to the actual terminals, this is strictly implementing the new NYE 568J-50-UV lubricant due to NYE Lubricants, Inc. replacement notification. This transition is estimated to start in April of 2016. If your customer requires PPAP for these new part numbers, please submit PPAP request on their behalf.

Reason for Changes:

Product improvement. NYE Lubricants, Inc. is superseding their 561J lube with 568J lube. NYE Lubricants, Inc. has sent out their own customer notifications and information fliers detailing this lube replacement. NYE's Replacement Overview Datasheet can be downloaded from their website at "http://www.nyelubricants.com/site/get_document.php?id=5581". These are the same lubes, just different component suppliers, so new part number for traceability. TE is starting the process of transitioning to the 568J lube effectively with this notification. This will be a running change using up current 561J lube and then transitioning to the 568J lube. This is an unavoidable change and must happen in timely manner to avoid product disruptions.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	04-APR-2016
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-DEC-2016

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1924955-1	NO						
1924955-2	NO						
1924955-3	NO						
1924955-5	NO						
2035170-1	NO						
2035334-1	NO						
2035334-2	NO						
2098165-1	NO						
2098762-1	NO						
2098762-4	NO						
2098762-5	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1924955-3	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1924955-1	NO						
1924955-2	NO						
1924955-5	NO						
2035170-1	NO						
2035334-1	NO						
2035334-2	NO						
2098165-1	NO						
2098762-1	NO						
2098762-4	NO						
2098762-5	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1924955-1	NO						
1924955-2	NO						
1924955-5	NO						
2035170-1	NO						
2035334-1	NO						
2035334-2	NO						
2098165-1	NO						
2098762-1	NO						
2098762-4	NO						