



Title of Change:	Packaging change for TO263 products.
Effective date:	24 May 2018
Contact information:	Contact your local ON Semiconductor Sales Office or < Christian.remoreras@onsemi.com >
Type of notification:	This Product Bulletin is for notification purposes only. ON Semiconductor will proceed with implementation of this change upon publication of this Product Bulletin.
Change category:	<input type="checkbox"/> Wafer Fab Change <input type="checkbox"/> Assembly Change <input type="checkbox"/> Test Change <input checked="" type="checkbox"/> Other: <u>Packaging</u>

Change Sub-Category(s):	<input type="checkbox"/> Material Change <input type="checkbox"/> Datasheet/Product Doc change <input type="checkbox"/> Manufacturing Site Change/Addition <input type="checkbox"/> Product specific change <input checked="" type="checkbox"/> Shipping/Packaging/Marking <input type="checkbox"/> Manufacturing Process Change <input type="checkbox"/> Other: _____
--------------------------------	--

Sites Affected:	ON Semiconductor Sites: ON Cebu, Philippines	External Foundry/Subcon Sites: None
------------------------	---	--

Description and Purpose:

ON Semiconductor, Cebu, Philippines announces the change in packaging for TO263 package in term of the number of empty for the leader and trailer tapes inside the reel.

This is to ensure that additional protection of the units near the reel hub from damage during mishandling of boxes (dropped) which result to lifted leads by increasing the number of empty pockets of the trailer tape.

	Trailer Empty pockets	Leader Empty Pockets
Current	55	70
Proposed Change	90	25

List of Affected Parts:

FDB070AN06A0-F085	FGB3040G2-F085
FDB075N15A-F085	HUF76419S3ST-F085
FDB14AN06LA0-F085	HUFA75639S3ST
FDB2532-F085	HUFA76645S3ST-F085
FDB7030BL	ISL9V2540S3ST
FDB8030L	ISL9V5036S3ST
FDB8442-F085	NDB6020P
FDB86360-F085	NDB6030PL
FDB8880	NDB6060L
FDB9406-F085	

"Please be informed that there may be Customer Specific parts impacted by this Notification, thus MPN & CPN info will not be reflected in the parts list of this Generic document. Instead please click the link to the addendum PCN copy provided in the email notification to see full list of affected products specific to your company."



Appendix A: Changed Products

Product	Customer Part Number
FDB070AN06A0_F085	
FDB075N15A_F085	
FDB14AN06LA0_F085	
FDB2532_F085	
FDB7030BL	
FDB8030L	
FDB8442_F085	
FDB86360_F085	
FDB8880	
FDB9406_F085	
FGB3040G2_F085	
HUF76419S3ST_F085	
HUFA75639S3ST	
HUFA76645S3ST_F085	
ISL9V2540S3ST	
ISL9V5036S3ST	
NDB6020P	
NDB6030PL	
NDB6060L	NDB6060LTR-ND