



## Product Change Notice

Micron PCN: 30845  
Date: 4/8/2013

---

<b>Type of Change:</b>	End of Life	
<b>Title of Change:</b>	Micron 90nm 128Mb P8P Parallel PCM Discontinuance	
<b>Description of Change:</b>	Micron 90nm 128Mb P8P parallel PCM is being discontinued with no replacements.	
<b>Reason for Change:</b>	Change in Market Demand, Optimization of Manufacturing Efficiency	
<b>Contact Information:</b>	<u>AMERICAS:</u> ARAVIND RAMAMOORTHY <a href="mailto:ARAMAMO@MICRON.COM">ARAMAMO@MICRON.COM</a>	<u>EMEA:</u> MAURIZIO BELTRAMELLO <a href="mailto:MBELTRAMELLO@MICRON.COM">MBELTRAMELLO@MICRON.COM</a>
	<u>ASIA-PACIFIC:</u> JINGWEN YANG <a href="mailto:JYANG@MICRON.COM">JYANG@MICRON.COM</a>	<u>JAPAN:</u> DAIGO TOYAMA <a href="mailto:DTOYAMA@MICRON.COM">DTOYAMA@MICRON.COM</a>

---

**Product Affected:** All Micron 90nm 128Mb P8P parallel PCM devices

### Affected Micro Part Numbers

---

NP8P128A13B1760E	NP8P128AE3B1760E
NP8P128A13BSM60E	NP8P128AE3BSM60E
NP8P128A13T1760E	NP8P128AE3T1760E
NP8P128A13TSM60E	NP8P128AE3TSM60E

---

<b>Micron Sites Affected:</b>	All Sites
<b>Last Time Buy:</b>	8-Oct-2013*
<b>Last Time Ship:</b>	8-Apr-2014

---

\* Orders placed prior to the LTB date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.